

BUILDING VENTILATION SOLUTIONS

Case Study Coil Replacement Burlington Street Office



Case Study - Burlington Street Office

The frost coil at the site was severely damaged, requiring us to design, manufacture, and install a new one. To overcome access constraints and stay within budget, we split the coil into two sections, allowing for easier installation and connection in the plantroom without compromising functionality.



Air Handling Unit - Frost Coil Replacement



Size Up, Design & Manufacture Frost Coil:

Upgraded to a modern, more efficient system for better control and automation.

Uninstall Frost Coil & Remove Associated Pipework:

Replaced to ensure optimal airflow, improving the unit's ventilation performance.

Install Coil In Two Sections:

Installed to ensure precise temperature monitoring and control within the pool area.

Connect Frost Coil To Associated Pipework:

Updated to enhance air regulation and distribution, improving indoor air quality.

Commission, Test & Tidy The Site:

Replaced to ensure smooth operation and to safeguard against potential airflow issues.

GET IN TOUCH WITH US

Our dedicated team is ready to assist you with your needs. Get in touch and we'll promptly respond to your inquiry. Don't hesitate to contact us for your personalised quote today!

*Unit 1, The Business Centre, Morgans Vale Rd,
Redlynch, Salisbury SP5 2HA*

CONTACT DETAILS

www.bvs-ltd.co.uk

[Tel: 01256 518170](tel:01256518170)

info@bvs-ltd.co.uk